

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS



**IMAGES ARE BEST AVAILABLE COPY.**


**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

24.11.2003 13:55 RHEINMETALL AG VRP → 010017186011099

NR.131 D14

22742





24.11.2003 13:55 RHEINMETALL AG URP → 010017186011099

NR.131 D15

22742




FIGURE 3




FIGURE 4

24.11.2003 13:55 RHEINMETALL AG URP -> 010017186011099 NR.131 016

22742




FIGURE 5




FIGURE 6

22742

FIG. 7B





FIG. 7D



FIGUR 7

FIG. 7C





FIG. 7A



22742




FIGURE 8




FIGURE 9




FIGURE 10




FIGURE 11

24.11.2003 13:55 RHEINMETALL AG URP → 010017186011099

NR.131 019

22742




FIGURE 12




FIGURE 13




FIGURE 14